

Estate: CHURCHILL PLACE/MILTON ROAD					
Names of person inspecting:	David Worrall (housing	Date of last inspection:	08/10/2024		
	Officer), Debra Doyle (Caretaking Supervisor), Otis Baptiste (Asset Management)	Date of current inspection:	28/05/2025		
Others in attendance (record					
status, eg. Councillor,					
resident, etc):					
Report circulated to					
Attendees plus					

# Repairs identified

Address/Location	Description of Defect/Action Required -		Repairs Reference	Repairs Target
		safety	No/s	Completion
CHURCHILL PLACE		concern?		Date
1 – 14	Floor tiles missing	Yes	TBC	PIT?
15 – 28	Blocked drain outside rear door of block – Full block drain maintenance to 1-42	Yes	WO0001028208	14/07/2025
15-28	Glass panes in main entrance door to be repaired/replaced	Yes	WO0001027532	12/06/2025
15-28	Downpipe missing outside front of block	Yes	WO0001028247	15/07/2025
43-56	Graffiti on external side of block to be removed	Yes	WO0001028312	15/07/2025
43-56	Broken glass panes x2 in main entrance door to be replaced.	Yes	WO0001027574	12/06/2025
43-56	Broken glass pane in rear entrance door to be replaced	Yes	WO0001028210	24/06/2025
43-56	Floor tiles on top floor to be replaced	Yes	TBC	PIT?
43-56	Lock to main entrance door not working	Yes	WO0001028211	24/06/2025
57-70	Floor tiles on ground floor to be replaced	Yes	TBC	PIT?
57-70	Defective/leaking overflow outside no. 62 or no. 54	Yes	WO0001028214	15/07/2025
71-84	Graffiti on external side of block to be removed	Yes	WO0001028313	15/07/2025

Address/Location  CHURCHILL PLACE	Description of Defect/Action Required -	Is this a Health and safety concern?	Repairs Reference No/s	Repairs Target Completion Date
85-98	Secure trunking to electrical wiring, 1 <sup>st</sup> floor by stairs	Yes	WO0001028212	
85-98	Floor tiling on stairs to be replaced	Yes	WO0001028249	24/06/2025
85-98	Adjustment to internal light sensor required. Area too dark during daylight hours – Referring to M&E as this would an upgrade and not maintenance	Yes	TBC	M&E
Garage area	Secure access to area below 57-70	Yes	WO0001028282	15/07/2025
MILTON ROAD				
1 – 6 All Clear	Trades button not working – tenants requested to switched off due criminal activity	Yes	N/A	N/A
7 – 10 All Clear				
Car park	Metal post needs resetting	Yes	WO0001028310	15/07/2025
Rear of blocks	Boundary fencing panel to be replaced, c. 1.5m H x 2m L	Yes	WO0001028274	15/07/2025

# Non-Repair issues identified

Address/Location	Description of Defect/ Action Required -	Is this a Health and safety concern?	Person/ team Action required from	Target Completion Date
Churchill Place				
1 – 14	Bikes under stairwell, rubbish outside flat 13	Yes	HO/Estate Svcs	Wait for date ES
1-14	Graffiti on all floors to be removed	Yes	Est. Services	Refer to repairs for internal repainting
15-28	Washing machine outside no. 27. Tenant to be instructed to move it	Yes	НО	TBC
15-28	Blocked rubbish chute, 2 <sup>nd</sup> floor	Yes	Est. Services	Done
15-28	Items on top floor to be removed	Yes	Est. Services	Done
15-28	Faeces outside front of block to be removed	Yes	Est. Services	Done
29-42	Bike outside intake cupboard & table outside no. 37 to be moved. HO to write to all residents re storing of items in communal areas	Yes	НО	TBC
29-42	Gas bottle by 2 <sup>nd</sup> floor chute to be removed	Yes	Est. Services	Done
43-56	Items outside 51, 52, 53 & 56 37 to be moved. HO to write to all residents re storing of items in communal areas	Yes	НО	TBC
57-70	Bike blocking intake cupboard door. HO to write to all residents re storing of items in communal areas	Yes	НО	TBC
57-70	Refuse by chute on 1st floor & on external area of top floor to be removed	Yes	Est. Services	Done
71-84	Refuse outside rear entrance door to be removed	Yes	Est. Services	Done

Address/Location	Description of Defect/ Action Required -	Is this a Health and safety concern?	Person/ team Action required from	Target Completion Date
71-84	Items outside no. 76. HO to write to all resident re storing of items in communal areas	Yes	НО	TBC
85-98	Items under stairs to be removed. HO to write to all residents re storing of items in communal areas	Yes	НО	TBC
Milton Rd				
1-6	Cabinet outside front of block and refuse in bin area to be removed	Yes	Est. Services	Done
7-12	Refuse by rear shed area and child's trampoline to be removed by stairs to roof access door	Yes	Est. Services	Rubbish removed

### **OUTSTANDING ACTIONS**

This is a list of works which were identified on the previous estate inspection report that remain outstanding

## **Outstanding Repairs**

Address / Location	Description of Defect/ Action Required -	•	Summary of actions taken to rectify (with dates) and current status

## Outstanding Non-Repair issues

Address / Location	Health and	Person / team Action required from	Target Completion Date
·			

Estate Action Plan		Name of Estate	
Where we receive requests for improvement which are not considered day to day repairs	•	•	problems such as anti-social behaviour and We call this an estate action plan.
We consider whether these items should be	e done and how we might fund the v	work.	
New Recommendations arising from the	is Estate Inspection (if made)		
□ None			
☐ New recommendations / suggestions			
Update on recommendations / proposal	Is from previous Estate Inspection	ns	
☐ None under consideration			
☐ Details on "works in progress":			
Inspections report completed by David Worrall	Signature	D	ate 04/06/2025