



EXTRACTOR FAN DETAILS

- 1- adjust blades exhaust canopy 3000mm diameter over canopy with 4 no. stainless steel and stainless steel grease filters. Filter must be replaced before a week.
- 2- Use fan and the steel will be naturally exhausted from the ceiling
- 3- Adjusted exhaust fan fan 3000mm diameter type motor fan provide (check size to extraction fan) 3. Exhaust panels must be replaced every 4-6 months.
- 4- 400mm x 100mm x 100mm 400mm stainless steel exhaust fan motor with stainless steel motor and stainless steel exhaust.
- 5- 400mm x 100mm 400mm fan fan to exhaust the motor fan to 10m high.
- 6- Provide grease extraction between steel and exhaust.
- 7- Extractor fan connection of the bakery oven according to the manufacturer's requirements

GENERAL NOTES

Provide and to all necessary protection for safety and protection of clients possessions.

Provide and to all necessary temporary support to ensure safe working until construction is complete.

Carry out all work in all possible protection. Provide suitable weather protection type to be agreed with client.

INTERNAL FINISHES

To be agreed on site with client.

PLASTERWORK

Apply 7 and 10mm lightweight plaster to all new internal brick or block walls.

Suitably support existing structure over as new opening is formed to take new beams or joists. Safe method of working to be prepared before undertaking all structural alterations.

Check all dimensions on site before work proceeds.

ALL PRODUCTS

To be BSA approved and listed BSI or manufacturers instructions. Any discrepancy with Towers notes must be reported to Towers before use or if possible before ordering.

1. Do not scale from this drawing.
 2. All dimensions to be checked on site before ordering materials or commencing work.
 3. In case of discrepancies in drawings, calculations or details refer to TOWERS ASSOCIATES for clarification. Similar decisions by contractors will not be accepted.
 4. For any information not covered by these drawings refer to TOWERS ASSOCIATES for clarification. Similar decisions by contractors will not be accepted.
 5. The contractor must ensure that work is being carried out in the latest revision of all the working drawings.
 6. It is the contractor's responsibility to inform the local authority before work commences on site, and of all proposed stages of work, all to the District Surveyors satisfaction.
 7. If work commences on site before full plans approval has been given, TOWERS ASSOCIATES accept no responsibility for any additional work or materials that the District Surveyor may require.
 8. This drawing and all copies produced there from remain the copyright and property of TOWERS ASSOCIATES. It may only be reproduced by TOWERS ASSOCIATES and all copies must be returned to TOWERS ASSOCIATES if approved.
- By using this drawing the user and his or her employer signify their agreement of the above terms and conditions.

Fire Precautions	
	Alarm Bell
	Alarm Call Point
	Heat Detector
	Smoke Detector
	Emergency lighting
	Fire Alarm Panel
	13 Amp Unswitched Spur with Neon Light. On Dedicated Supply
	Fire Extinguisher 9 Ltr water
	Fire Extinguisher 2.73Kg Carbon dioxide
	Fire Extinguisher 5 kg carbon dioxide.

The area of alcohol to scale or store

STANDARD FIRE SIGNS TO BS5499

- To Fire Exit
- Fire door Keep Shut
- Fire Escape Keep Clear
- Fire Exit
- From Viking Signs 0855271625
- To be installed to BS 5266 Emergency Lighting

REV. DATE	DESCRIPTION
A	MAR 12
	Door note added. Emergency light added to grid where added to mezzanine floor.
JOB	
63-65 Station Road, North Harrow,	
TITLE	
FIRE PRECAUTIONS LAYOUT	
DRG. No.	REV. A
2698-20	
SCALE	DRN BY/PDN
1:50	
	DATE
	Mar 12
	CHECKED
	DATE
TOWERS ASSOCIATES	
Harefield Oil Terminal, Harvil Rd, Harefield, MIDDX UB9 6JL	
Fax 01895 814664	
Tel 01895 812822	