

Estate: Northolt Park –	Silverdale Close, The Heights, Mar	tin Drive, Gaylor Road, Do	oncaster Drive & Gardens.
Name of person inspecting:	David Worrall (Housing Officer), Emma Davies (Senior Caretaker), Priyangen	Date of last inspection:	20/05/2025
	Mangalaruban (Repairs & Maintenance), Otis Baptiste (Communal Lead)	Date of current inspection:	11/11/2025
Others in attendance (record status, eg. Councillor, resident, etc):	Cllr Jerry Miles		·
Report circulated to Attendees plus	Otis Baptiste, Priyangen Mangalaruban		

Repairs identified

Address / Location	Description of Defect/ Action Required –	Is this a Health and safety concern?	Repairs Reference No/s	Repairs Target Completion Date
BLK 1-3 Karatina Court, 199a The Heights, Northolt, UB5 4BU	No push bar on fire door (otherwise nice and clean)		Peter Goodwin	
BLK 201-207 The Heights, The Heights, Northolt, UB5 4BX	No issues (just external contract scaffolding present in front of the block)		N/A	
BLK 220-230 The Heights, The Heights, Northolt, UB5 4BX	Second floor communal light flashing (light is green and red); first floor light is dim and third floor communal light not working		M&E	
BLK 2-7 Silverdale Close	Broken manhole cover in front of block		WO000103 8719	31/12/2025



Address / Location	Description of Defect/ Action Required –	Is this a Health and safety concern?	Repairs Reference No/s	Repairs Target Completion Date
SBLK 8-13 Silverdale Close, Silverdale Close, Northolt, UB5 4BL	Minor decoration (Flaking paint on wall on left as you enter; and wall needs smoothing and painting since flaking paint on stairwell)		WO000103 8720	31/12/2025
BLK 14-19 Silverdale Close, Silverdale Close, Northolt, UB5 4BL	Minor decoration (Wall plaster cracked on stairwell and wall cracked on the left as you enter the block)		WO000103 8722	31/12/2025
BLK 14-19 Silverdale Close, Silverdale Close, Northolt, UB5 4BL	Bubbling path (flooring needs redoing) – requires a programme to do all blocks		TBC	
BLK 14-19 Silverdale Close, Silverdale Close, Northolt, UB5 4BL	Uneven manhole cover near to block		WO000103 8723	31/12/2025
2-6 Gaylor Road	Replace guttering, downpipes and facias, front and back of properties – CAPH		WO000103 2664	05/01/2026



Non-Repair issues identified

Address / Location	Description of Defect/ Action Required –	Is this a Health and safety concern?	Person / team Action required from	Target Completion Date
BLK 2-7 Silverdale Close	Overgrown ivy and missing shed door	NO	Pass to Secure Parking and Storage for door and housing estates for ivy	
BLK 8-13 Silverdale Close	Laptop chair in front of flat 10 sitting in front of the door	YES (Health and Safety)	David HO to notify tenant to clear then remove goods	
BLK 8-13 Silverdale Close	Suitcases and box next to flat 8	NO	David HO to notify tenant to clear then remove goods	
BLK 14-19 Silverdale Close, Silverdale Close, Northolt, UB5 4BL	Fly tipped rubbish next to flat (needs to be cleared)	NO	Housing Estate Services to deal with	



OUTSTANDING ACTIONS

This is a list of works which were identified on the previous estate inspection report that remain outstanding

Address / Location	Description of Defect/ Action Required –	Is this a Health and safety concern?	Repairs Reference No/s	Summary of actions taken to rectify (with dates) and current status

Outstanding non-repair issues

Address / Location	Description of Defect/ Action Required –	Is this a Health and safety concern?	Person / team Action required from	Target Completion Date



Estate Action Plan		Name of Estate			
Where we receive requests for improvements / replacement of items or identify work to prevent specific problems such as anti-social behaviour and which are not considered day to day repairs, a list of suggested improvements for each estate is kept. We call this an estate action plan.					
We consider whether these items should be done an	d how we might fund the v	vork.			
New Recommendations arising from this Estate	Inspection (if made)				
□ None made					
☐ New recommendations / suggestions:					
Update on recommendations / proposals from p	revious Estate Inspectio	ns			
□ None under consideration					
☐ Details on "work in progress":					
Inspection report completed by	Signature		Date		